Weathertzation Assistance Program

Work Order (Bid Form)

WORK ORDER INFORMATION

Work Order Name: 14014SO2039Work Order Type: WeatherizationAudit Name: 14014SO2039

CLIENT INFORMATION

Client Name: Address:

Client ID: 14014SO2039 WINCHESTER, TN 37398

Alt. Client ID: FRANKLIN

AGENCY INFORMATION

Agency: SOUTH CENTRAL HUMAN RESOURCE AGENCY Agency Phone: (931) 433-7182

Address: 1437 WINCHESTER HIGHWAY Fax: (931) 438-0074

Company Name & License Number:	
Contractor's Signature:	

<u>COMMENT</u>

Client Name:
Client ID: 14014SO2039
Alt. Client ID: FRANKLIN

Work Order (Bid Form)
Work Order Name: 14014SO2039

Report Run On: 5/14/2010

DOE Weatherization Assistant Version 8.5.0

Page 1 of 5

Measure 1 Inf	iltration Redctn			Componen	ts		1	Inspected
	ERIOR AIR SEAL - PLUM JLK ALL WINDOWS	BING AND	ELE(CTRICAL				
3. INS	TALL NEW DOOR LOCK	ON FROM	IT DO			DOOR		
				Estimated	<u> </u>		Actual	
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Miscellaneous Supplies	Infiltration Reduction	Each	1					
2 Labor	LABOR	Hour						
Other Detail						_		
			Measur	e Sub Total:] ;	Sub Total:	
Field Notes:								
Measure 2 DV Comment	VH Pipe Insulation			Componen				Inspected
Comment	·			Estimated	<u> </u>		Actual	
Comment # Material / Labor	Description / Comment	Units	Qty	•		Qty		Inspected
	·	<i>Units</i> Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor	Description / Comment			Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Insulation	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	1	Estimated	<u> </u>	Qty	Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated	<u> </u>		Actual	
Comment# Material / Labor1 Insulation2 Labor	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	
# Material / Labor 1 Insulation 2 Labor Other Detail	Description / Comment DHW Pipe Insulation	Each	1 1	Estimated Unit Cost	<u> </u>		Actual Unit Cost	

Report Run On: 5/14/2010

Measure 3 Floo Comment	Components F1						Inspected	
#		11.20		Estimated			Actual	T . 4 . 4
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Insulation	Floor Insulation - Fiberglass Batts - R-19	SqFt	1053					
2 Labor	Floor Insulation - Fiberglass Batts - R-19	SqFt	1053					
Other Detail								
			Measur	e Sub Total:		,	Sub Total:	
Field Notes:								
	Improper Venting (Cloth	nes Dryer)	Componen				Inspected
Measure 4 Fix Comment		·		Estimated	1	Oftv	Actual	
Measure 4 Fix Comment # Material / Labor 1 Health and Safety	Description / Comment	nes Dryer <i>Units</i> Each	Qty	•		Qty		Inspected
Measure 4 Fix Comment # Material / Labor 1 Health and Safety Items	Description / Comment	Units	Qty	Estimated	1	Qty	Actual	
Measure 4 Fix Comment # Material / Labor 1 Health and Safety	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Fix Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Fix Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1	Estimated	1	Qty	Actual	
Measure 4 Fix Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Metal Flex	<i>Units</i> Each	Qty 1 1	Estimated	1		Actual	

Report Run On: 5/14/2010

	L NEW ATTIC ACCESS (COVER A	AND FF	RAME IN / II	NSTALL 2	2		
=,	ES AND W/S							
				Estimated	<u> </u>		Actual	I
# Material / Labor	Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
Construction Materials/Hardwar e	ATTIC ACCESS COVER	Each	1					
2 Labor	LABOR	Hour						
3 Construction Materials/Hardwar e	ATTIC LATCHES	Each	2					
4 Labor	LABOR	Hour						
Other Detail						1		
			Measur	e Sub Total:			Sub Total:	
	oke Detector is Needed			Componen	ts		ı	Inspected
	oke Detector is Needed			Componen Estimated			Actual	Inspecte
Comment	oke Detector is Needed Description / Comment	Units	Qty	•		Qty		Inspected
Comment Material / Labor		<i>Units</i> Each		Estimated	<u> </u>	Qty	Actual	
Comment Material / Labor Health and Safety Items	Description / Comment		Qty	Estimated	<u> </u>	Qty	Actual	
Comment Material / Labor Health and Safety Items Labor	Description / Comment Smoke / Carbon detector	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment Material / Labor Health and Safety Items	Description / Comment Smoke / Carbon detector	Each	Qty 1	Estimated	<u> </u>	Qty	Actual	
Comment # Material / Labor 1 Health and Safety Items 2 Labor	Description / Comment Smoke / Carbon detector	Each Hour	Qty 1 1	Estimated	<u> </u>		Actual	

Report Run On: 5/14/2010

Mea	sure 7	Vapor Barrier Needed (Basement/Crawlspace)			Componen	ts		ı	nspected
Com	ment								
					Estimated	<u> </u>		Actual	
# Ma	terial / Lab	or Description / Comment	Units	Qty	Unit Cost	Total	Qty	Unit Cost	Total
1 Ins	ulation	Basement / crawlspace vapor barrier	Each	1					
2 Lab	oor	Labor	Hour	1					
Othe	r Detail								
				Measur	e Sub Total:] ,	Sub Total:	
Fiel	ld Notes:								
			Work Or	der Gra	nd Total:		Gran	d Total:	